The influence of the structure on the fatigue properties of aluminium alloys for the casting

Milan Uhrčík^{1,}, Peter Palček¹, Mária Chalupová¹, Martin Frkán¹*

¹University of Žilina, Faculty of Mechanical Engineering, Department of Materials Engineering, Univerzitná 8215/1, 01026 Žilina, Slovakia

Abstract. The article will be focused on monitoring the influence of the structure on the fatigue properties of Al-Mg cast alloy. As an experimental material were used aluminium alloys EN AC 51200 and EN AC 51500, supplied in a cast state without a heat treatment, which were produced by the continuous casting method. These alloys were selected on the basis of the chemical composition, where the content of most alloying elements is comparable. Fatigue properties of aluminium alloys were tested by three-point bending cyclic loading. The fracture surface of the testing sample was examined using scanning electron microscopy (SEM), where samples were observed on various stages of the fatigue process, their characteristics and differences of fracture surfaces.

Keywords: fracture surface, Al-Mg cast alloy, structure

1 Introduction

Aluminium alloys with magnesium as the major alloying element constitute a group of heat treatable alloys with medium strength, high ductility, excellent corrosion resistance and weldability [1-3]. Wrought Al-Mg alloys are used as structural materials in marine, automotive, aircraft and cryogenic applications while the cast forms are used mainly for their corrosion resistance in dairy, food handling and chemical processing applications. Unlike the heat treatable alloys, these materials derive their strength primarily from solid solution strengthening by Mg, which has a substantial solid solubility in aluminium. However, in order to obtain strength levels approaching the regime of the precipitation hardening alloys, high Mg levels are required. Such high levels of Mg pose processing challenges and can increase the susceptibility of the alloys to stress corrosion cracking [3-6]. Fatigue failures in metallic structures are a well-known technical problem. In a specimen subjected to a cyclic load, a fatigue crack nucleus can be initiated on a microscopically small scale, followed by crack grows to a macroscopic size, and finally to specimen failure in the last cycle of the fatigue life. Understanding of the fatigue mechanism is essential for considering various technical conditions which affect fatigue life and fatigue crack growth, such as the material surface quality, residual stress, and

* Corresponding author: milan.uhrcek@fstroj.uniza.sk

Reviewers: *Richard Pastirčák, Marta Kianicová*

environmental influence. This knowledge is essential for the analysis of fatigue properties of an engineering structure [7-9].

2 Material characteristics

As an experimental material were used aluminium cast alloys of type Al-Mg (EN AC-51200 and EN AC-51500), supplied in a cast state without a heat treatment in the form of plates (Fig. 1). They were produced by the continuous casting method. Test samples for determining the fatigue properties were made by the cutting operation from these plates, which were cut from casts (Fig. 2). The chemical composition of both alloys was examined by spark emission spectrometer SPECTROMAXx and results are shown in the Table 1. These alloys were selected based on this chemical composition, where the content of most of alloying elements is comparable, only a concentration of magnesium is considerably different.

Fig. 1. The plate cut from a casting

Fig. 2. The sample for a fatigue test

Table 1. The chemical composition of alloys, in wt. %.

	Si	Fe	Cu	Mn	Mg	Cr	Pb	Al
EN AC 51200	1.3	0.102	0.003	0.416	10.32	0.006	0.027	balance
EN AC 51500	1.53	0.11	0.004	0.529	6.28	0.008	0.031	balance

These materials have excellent corrosion resistance, very good workability, polishability and good weldability. The advantage of these alloys is that they are used without a heat treatment, thereby saving the costs of production of parts. Products from these alloys are mainly produced by high pressure casting method.

3 Experimental methodology

3.1 Metallographic analysis

Preparation of samples, which need to be given a very good attention because of its quality depends on the quality of the analysis of structures, consisted of the following operations:

Cutting – Specimens for metallographic analysis were taken from supplied plates, using a precision automatic saw MTH MIKRON 3000. Samples were cutting without damage by deformation or without heat affection.

Preparation – For the sample preparation was used a hot mounting equipment STRUERS CITOPRESS and mixtures Dentacryl and Bakelite. Pressing of samples took about 3 minutes at temperature 180 °C and pressure 25 MPa.

Grinding – After mounting of samples, they were grinded by using a semiautomatic equipment TEGRASYSYSTEM. For this operation were used two abrasive discs with a various grain size. The rough grinding was done by an abrasive disc with a grain size 500 and for the fine grinding was used an abrasive disc with a gain size 1200. Both grinding was carried out for 1 minute. During this operation, discs were wetted with water to prevent the heat affected of samples.

Polishing – It was also performed on a semiautomatic machine TEGRASYSYSTEM and it was carried out in three steps. In the first step of polishing, it was used a polishing disc MDMol with a suspension DiaProMol, in the second step was used a disc MDNap with a suspension DiaProNap and in the last step was used a disc MDChem with a paste OP-S.

Etching – Samples were etched with 0.5% hydrofluoric acid solution for 10 seconds.

The thus prepared samples were used for metallographic analysis, using a light metallographic microscope NEOPHOT 32.

3.2 Fatigue tests

Fatigue tests were carried out on the test equipment ZWICK/ROELL AMSLER 150 HFP 5100 (Fig. 3) according to norm STN 42 0363. This equipment is using the resonance principle with constant or variable amplitude and mean load. Smooth rectangular specimens without notches (10x18x40 mm) (Fig. 2) were loaded by cyclic three-point bending loading with mean stress $\sigma_m = -144$ MPa and frequency 120 Hz.

Fig. 3. The test equipment ZWICK/ROELL AMSLER 150 HFP 5100

3.3 Fractography

Fractographical assessment of fracture surfaces was realized on samples from each material after the fatigue test. On samples were observed various stages of fatigue process, their characteristics and differences of fracture surfaces between samples loading in high and low amplitude of stress. It has also been observed an area of final fracture. Fracture surfaces were evaluated by scanning electron microscopy TESCAN VEGA LMU II.

4 Results and discussion

4.1 Microstructural analysis and phase analysis

Considering that alloys were casted under the same technological conditions, it can be said that the structure affects only the chemical composition of alloys. Microstructure of materials is expressively dendritic (Fig. 4). The highest percentage representation of

dendrites has α -phase (matrix) that is a solid solution of aluminium together with other additive elements. In the structure, there is also an intermetallic phase Mg_2Si . This phase has a different morphology in alloys. In the case of EN AC 51200 alloy, it has a shape of skeleton formation and is distributed in interdendritic areas. There is also β -phase, which is formed in interdendritic areas and has a stoichiometric basis Al_3Mg_2 . In alloy EN AC 51500, intermetallic phase Mg_2Si has a finer morphology and does not have a typical shape of skeleton formation.

Because elements such as iron and manganese are also in alloys, can be observed a small amount of Fe-rich phase in structure of both materials, probably $Al_6(FeMn)$. β -phase is not present in this alloy, because of the smaller content of magnesium.

Fig. 4. Microstructures of aluminium alloys

For identification and confirmation of structural components was used square and line analysis. Results are shown in Fig. 5 – Fig. 8.

Fig. 5. Identification of structural components of aluminium alloy EN AC 51200 – a square analysis

Fig. 6. Identification of structural components of aluminium alloy EN AC 51200 – a line analysis

Fig. 7. Identification of structural components of aluminium alloy EN AC 51500 – a square analysis

Fig. 8. Identification of structural components of aluminium alloy EN AC 51500 – a line analysis

It was also made a percentage assessment of shares of individual phases (Fig. 9 and Fig. 10). Results are shown in the Table 2. It can be concluded that the phase $\text{Al}_6(\text{FeMn})$ is comparable in both alloys. Mg_2Si phase is about 4% higher in alloy EN AC 51500. This phase can improve the hardness and tensile strength, but can also aggravate the fracture toughness and the ductility, depending on the morphology and the amount. Only the alloy EN AC 51200 contained the β -phase, in an amount of 8%. This phase is a brittle and reduced ductility at temperatures below 350°C.

Fig. 9. A measuring of percentage assessment of phases in the alloy EN AC 51200

Fig. 10. A measuring of percentage assessment of phases in the alloy EN AC 51500

Table 2. A percentage assessment of phases in alloys [%].

	Al ₃ Mg ₂	Mg ₂ Si	Al ₆ (FeMn)	α-phase
EN AC 51200	8	7	0.7	balance
EN AC 51500	0	11	1.2	balance

4.2 Fatigue lifetime

Alloys EN AC 51200 and EN AC 51500 were loaded by cyclic three-point bending loading with the same parameters, only stress amplitude was changing. From results of fatigue tests were constructed graphs σ_a -N in semi-logarithmic coordinates, for every alloy (Fig.11 and Fig. 12). By comparing of graphs can be stated that alloy EN AC 51500 has better fatigue properties than alloy EN AC 51200 in analyzed area of the number of cycles.

Fig. 11. Results of fatigue tests for alloy EN AC 51200

Fig. 12. Results of fatigue tests for alloy EN AC 51500

4.3 Fatigue lifetime

Fracture surfaces of test specimens were evaluated at first in term of macrofractographic. From this analysis it is possible to determine initiation (nucleation) of fatigue crack, surfaces of individual areas of fracture, namely the fatigue fracture area and the area of static final failure.

A general view of the fracture area for the alloy EN AC 51500 after 1314148 cycles at a stress of 120 MPa it documented in Fig. 13a, where can be seen various stages of fatigue process. Detail of initiation site is shown in Fig. 13b. Transgranular fatigue failure of α-phase (matrix) and there were observed typical signs of fatigue – striations and also an interfacial and a cleavage mechanism and failure of Mg₂Si phase, this all is shown in Fig. 13c. Fig. 13d displays the area of static final failure, where can be seen plastic’s transformed ridges of α-phase, together with a transgranular ductile fracture of α-phase with dimple morphology and also is visible an interfacial failure of Mg₂Si phase.

Fig. 13. Fracture surface of aluminium alloy 51500, $\sigma_a = 120$ MPa, $N_f = 1314148$ cycles

A general view of the fracture area for the alloy EN AC 51500 after 799229 cycles at a stress of 138 MPa is shown in Fig. 14a. Here can be seen that when higher amplitude of stress was applicate, the fatigue crack was spread from several initiation sites on the specimen surface and there was also a reduction of the fatigue area. Detail of one initiation site is shown in Fig. 14b. Transgranular fatigue failure of α -phase (matrix) and there were observed typical signs of fatigue – striations a it is shown in Fig 14c. Fig. 14d displays the area of static final failure, where can be also seen plastic's transformed ridges of α -phase, together with transgranular ductile fracture of α -phase with dimple morphology and also is visible an interfacial failure of Mg_2Si phase.

Fig. 14. Fracture surface of aluminium alloy 51500, $\sigma_a = 138$ MPa, $N_f = 799229$ cycles

A general view of the fracture area for the alloy EN AC 51200 after 761899 cycles at a stress of 124 MPa is documented in Fig. 15a, where can be seen various stages of fatigue process. Detail of initiation site is shown in Fig. 15b. In Fig 15c can be seen an interfacial failure of intermetallic phases (Al_3Mg_2 , $Al_6(FeMn)$ and Mg_2Si) and also a transgranular fatigue failure of α -phase (matrix). Fig. 15d displays the area of static final failure, where can be seen interfacially broken intermetallic phases and plastic's transformed ridges of α -phase, together with transgranular ductile fracture of α -phase with dimple morphology.

Fig. 15. Fracture surface of aluminium alloy 51200, $\sigma_a = 124$ MPa, $N_f = 761899$ cycles

A general view of the fracture area for the alloy EN AC 51200 after 150530 cycles at a stress of 139 MPa is shown in Fig. 16a. Here can be seen that when higher amplitude of stress was applicate, the fatigue crack was spread from several initiation sites on the specimen surface and there was also a reduction of the fatigue area and a smaller number of cycles to fracture. Detail of one initiation site is shown in Fig. 16b. In Fig 16c can be seen a transgranular fatigue failure of α -phase (matrix) and also an interfacial failure of intermetallic phases (Al_3Mg_2 and $Al_6(FeMn)$). Fig. 16d displays the area of static final failure, where can be seen plastic's transformed ridges of α -phase, together with a transgranular ductile fracture of α -phase with dimple morphology and also is visible an interfacial failure of Mg_2Si and Al_3Mg_2 phases.

Fig. 16. Fracture surface of aluminium alloy 51200, $\sigma_a = 139$ MPa, $N_f = 150530$ cycles

Conclusion

On the basis of performed experimental fatigue tests can be drawn following conclusions:

- Square and line analysis showed, what elements and phases are found in selected alloys.
- Alloys have a clearly dendritic structure consisting mainly α -phase. In the structure of both alloys are intermetallic $Al_6(FeMn)$ and Mg_2Si phases. In alloy EN AC 51200, there is also an intermetallic Al_3Mg_2 phase.
- Alloys are different in terms of morphology and amount of intermetallic Mg_2Si phase. The alloy EN AC 51200 has this phase in a shape of skeleton formation in the amount of 7%. In the case of alloy EN AC 51500 is a finer morphology of this phase and the percentage is 11%.
- Alloys are comparable in terms of morphology and the amount of $Al_6(FeMn)$ phase.
- From fatigue tests, it can conclude that alloy EN AC 51500 has better fatigue properties than alloy EN AC 51200, in the analyzed areas of number of cycles under the same conditions of loading.
- Fractographic analysis did not reveal significant changes of micromechanisms of fracture surfaces after fatigue tests. Fatigue area is characterized by transgranular fatigue failure of α -phase (matrix). Intermetallic phases in this area were violated

interfacially, only Mg_2Si phase had also the cleavage mechanism and failure somewhere. The area of static final failure is typical of a transgranular ductile fracture of α -phase with dimple morphology with plastic's transformed ridges. When comparing both of alloys, it can be stated that the only difference is that on the fracture surface of alloy EN AC 51500 is not an interfacially broken Al_3Mg_2 phase, because this alloy does not contain it.

- In terms of stress amplitude can be said that in case of a higher amplitude of cyclic loading there was a multiple initiation of fatigue crack.

From the analysis of the influence of the structure on the fatigue properties, it can be stated that the alloy EN AC 51500 has better fatigue properties due to a smaller amount of intermetallic phases, which are finer.

This study has been supported by the Scientific Grant Agency of the Ministry of Education of the Slovak Republic VEGA 01/0683/15 and VEGA 01/0533/15.

References

1. I. J. Polmear, *Light alloys-metallurgy of the light metals*. London (1995)
2. L. Hurtalová, E. Tillová, *Elimination of the negative effect of FE-rich intermetallic phases in secondary (recycled) aluminium cast alloy*. *Manufacturing Technology* **13** (1), 44-50 (2013)
3. *ASM metals handbook, properties and selection: nonferrous alloys and special-purpose materials*. Ohio, USA (1990)
4. S. Lathabai, P. G. Lloyd. *Acta Materialia* **50** (17), 4275-4292 (2002)
5. V. Zatkalíková, L. Markovičová, J. Belan, T. Liptáková, *Variability of local corrosion attack morphology of AISI 316Ti stainless steel in aggressive chloride environment*. *Manufacturing Technology* **14** (3), 493-497 (2014)
6. B. Hussey, J. Wilson, *Light alloys*. London (1998)
7. J. Belan, L. Hurtalová, A. Vaško, E. Tillová, *Metallography evaluation of IN 718 after applied heat treatment*. *Manufacturing Technology* **14** (3), 262-267 (2014)
8. F. Nový, V. Zatkalíková, O. Bokůvka, K. Miková, *Gigacycle fatigue endurance of marine grade stainless steels with corrosion pits*. *Periodica Polytechnica: Transportation Engineering* **41** (2), 99-103 (2013)
9. C. Bathias, *Fatigue in the very high cycle regime*. Vienna, Austria (2001)